

# General Environmental Incident Summary

**Incident:** 4117      **Date/Time Notice:** 6/5/2016      **DEM Incident No:**  
**Responsible Party:** Sterling Constructin Management, LLC.  
**Date Incident:** 6/3/2016      **Time Incident:**      **Duration:**  
**County:** Dunn      **Twp:** 147      **Rng:** 96      **Sec:** 19      **Qtr:**  
**Lat:** 47.54345      **Long:** -102.95300      **Method:** Navigation quality GPS  
**Location Description:** Bear Creek Pipeline Spread 2: From Killdeer, ND travel northwest on ND-22 (8.5 mi), Turn left onto 4th St NW (1.1 mi), Continue onto Gap Rd (2.3 mi).

**Submitted By:** Chase Edmiston      **Affiliation:**  
**Address:** 100 W Fifth St  
**City:** Tulsa      **State:** OK      **Zip:**

## Received By:

### Contact Person:

10020 HWY 200 East  
Dunn Center, ND

**Distance Nearest Occupied Building:**      **Release Contained:** Yes

**Type of Incident:** Equipment Failure

**Description of Released Contaminant:** hydraulic fluid

**Volume Spilled:**

**Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown

**Reported to NRC:** Unknown

### Cause of Incident:

ditch cave in on padding machine

### Risk Evaluation:

N/A

**# of Fatalities:**      **# of Injuries:**      **Affected Medium:** 03 - soil

### Potential Environmental Impacts:

localized soil contamination, no other sensitive resources affected.

### Action Taken or Planned:

The spill was contained using a spill kit. The contaminated soil was shoveled into sand bags and transported to the Sterling yard for disposal. No resources were affected.

### Wastes Disposal Location:

### Agencies Involved:

## **Updates**

---

**Date:** 6/6/2016      **Status:** Reviewed - Follow-up Required

**Author:** Souder, Taylor

**Updated Volume:**

**Notes:**

Further follow-up needed.

---

**Date:** 8/4/2016      **Status:** No Further Action Requested

**Author:** Washek, Sandi

**Updated Volume:**                      0.50 gallons

**Notes:**

Arrived on site at 10:14 a.m. accompanied by company representative. Weather was overcast with temperature 69 degrees F. The report indicated the padding machine had a hydraulic leak on pipeline row. The area surrounding the site is pastureland. Inspection of the soil showed no visible staining of the soil. No water was impacted. No additional follow-up needed.